
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————										
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length			
S1028-054	Smoke	9/5/2008	ADS/TM	S13CC1012MH	Dry	Yes	539.78			



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————											
Test ID Test Type		Date Inspected	Company / Super.	Blower MH		Ground Condition	Notification Made?	Total Length			
S1028-054	Smoke	9/5/2008	ADS/TM	S13C0	1012MH Dry		Yes	539.78			
Isolated Pi	pes ———										
Pipe ID		Upstream MH	Downstream	m MH	Length (ft)	Diam (I					
S13CC10)12G1	S13CC1012MH S13CC1030		0MH	278.1684	1 2	22				
S13CC10)19G1	S13CC1019MH	S13CC101	2MH	261.611	1 2	22				

Observations & Photos

No smoke was observed during this test.